# TRX II



Portable documenting calibrator

- Simulates and Read RTD's and thermocouples
- Sources and reads Millivolts, Volts, Milliamps, Ohms and frequency
- Measures pressure -1 to 700 Bar
- Dual readout: measure and source
  - Data storage for field calibrations
    - Data transfer via RS 232 or PCMCIA card



# TRXII

### Portable documenting calibrator

### A new standard for portable multifunction calibrators

The Druck TRX II portable documenting calibrator is the culmination of many years of combined field experience with the Druck and Unomat series of calibrators.

This one self-contained, battery powered package simulates and measures RTD's thermocouples and resistance, as well as souring and reading milliamps, millivolts, volts and frequency. The rugged design includes an impact resistant enclosure which is fastened to the carrying case for convenience and safety. Dedicated alphanumeric and documenting keypads surround a large LCD panel with dual readout and backlight. Connectors for source and measure are kept separate and a 24V output is provided for loop power.

The TRX II's extensive measurement capabilities can include pressure measurement by connecting Druck pressure sensors which have been digitally characterised to give high accuracy.

This highly accurate and easy to use documenting calibrator gives improved data quality and quicker calibration time since data can be uploaded and downloaded via the PCMCIA card or the RS232 interface.

### High performance and multi-functional

Typical accuracies: 0.01% reading ±0.01% FS for mA

measurement.

0.05% FS for pressure measurement

Measure: mA, mV, volts, T/C's RTD's pressure,

ohms, frequency and switch state.

Source: mA, mV, volts, T/C's RTD's ohms and

frequency

Remote pressure sensors: 70 mbar to 700 bar including gauge,

absolute and differential

Loop power: 24 Vdc

Data storage: 1 Mbyte and 2 Mbyte PCMCIA cards

Data transfer: RS 232 or PCMCIA card

### Simple to operate


The combined Druck and Unomat knowledge of customer needs, and innovative design, results in a high performance, yet easy to operate, multi-function documenting calibrator.

The key to the simple operation of the TRX II is the structured menu. Input and output readings are displayed simultaneously for test modes such as T-I and P-I, allowing quick comparison of the values. Used in conjunction with Linkpak-W calibration software, the TRX II will perform automatic calibrations from pre-defined procedures, calculating and reporting errors to the operator and storing the results on a PCMCIA card. This intuitive approach, whether used manually or automatically, ensures correct set up for the job at hand and improves working efficiency and data accuracy.

The TRX II provides simple and flexible data transfer to fit in with most working practices. Information can be reviewed on screen or transferred to and from the TRX II using the RS 232 interface. Alternatively, without docking the instrument to a PC, data can be transferred by exchanging PCMCIA cards.

The operating system works in several languages and provides scaling, step and ramp features for calibration and maintenance. The TRX II, which includes extensive self-test routines, can be relied upon time and time again for field calibration in extreme conditions.





# TRXII

### **Applications**

### MULTIFUNCTION PORTABLE CALIBRATOR

The TRX II has been designed for ease of use whilst meeting a wide range of application needs including calibration, maintenance and commissioning. The dual parameter display shows the measured and sourced values in large clear digits with all applicable information such as the units of measurement and range. With safety in mind, construction of the shoulder strap allows hands free operation whilst maintaning display visibility.

### Some of the capabilities

- Measure/source mA
- Measure/simulate 12 types of T/C
- Measure/simulate 9 type of RTD
- Measure/source frequency and pulses
- Simulate transmitter input and measure transmitter output
- Measure/source mV/V
- Measure/source resistance
- Measure pressure: -1 to 700 bar
- Test swiches: captures values on contact change

### Easy to operate

The easy to operate menu driven software enables the calibrator to be set up very quickly. Simply scroll through the menus and select the appropriate parameters.

Operating and connection errors such as loop resistance mismatch and cold junction temperature sensor absence are reported. The KEYSTROKING memory enables instant recall of previously stored user tests.



### TEMPERATURE SENSOR SIMULATION AND LOOP CHECKING

The auto step and ramp modes enable a single technician to test and commission control loops. The calibrator is left to generate a pre-programmed output, while the technician checks the signal further down the loop.

End to end control loop performance can be checked with one instrument by simulating a temperature signal at the start of the loop.





### TEMPERATURE TRANSMITTER SIMULATION AND CALIBRATION




Direct connection of thermocouple compensation wires eliminates the need for special connectors and reduces additional cold junction errors. This is the most reliable and accurate method of monitoring cold junction temperatures in a portable field calibrator.

In calibration mode the display shows all the required information. Both mV and mA values are displayed in °C for easy comparison, along with the calculated error expressed as % of span or reading.

The TRX II will simulate the temperature signal to the transmitter to be calibrated and will simultaneously measure and display the output. A 24 volt power supply is provided for stand alone operation.



The connection of 2, 3 and 4 wire RTD's is detected automatically, a feature unique to Druck's portable field calibratos



### CALIBRATION FOR ISO 9000







Dedicated keys for documenting field calibrations eliminate human errors. The 'AS FND' (as found) and 'AS LEFT' keys start the respective procedures for storing calibration data which can be recalled using the 'VIEW' key.

PCMCIA cards represent the most efficient data transfer media. Docking of the calibrator with the PC is unnecessary as a card containing calibration data can be exchanged for another containing new procedures/work orders, enabling technicians and calibrators to spend more time in the field.

Data is transferred to the PC from the PCMCIA card or the RS 232 interface for analysis, certificate printing and archiving. Exporting facilities are provided for wordprocessor and spreadsheet applications or inhouse maintenance systems.



Remote pressure sensors offer a cost effective means of expanding the capabilities of the TRX II, for example:

- Calibration of pressure transmitters
- Testing pressure switches
- For differential pressure applications
- For flow measurement calibrations

The capability of the TRX II can be extended by adding up to 8 external pressure sensors (connected one at a time). With ranges from 70 mbar to 700 bar and all welded stainless steel construction, sensors can be chosen to suite many applications. For convenience a single detachable cable assembly (part No. 230) connects any of the standard remote pressure sensors to the TRX II. Druck has applied the latest technology and production techniques to develop these sensors which are digitally corrected for non-linearity and temperature effects.

### **Specifications**

Over 50 sensor ranges are available including gauge, absolute and differential versions and with accuracy better than 0.05% FS (70mbar range 0.1% FS) even the most up to date pressure instrumentation can be maintained and calibrated.

### Pressure ranges (optional)

			(-
Gauge			Part No.
- 70 -	70	mbar	# 800
-175 -	175	mbar	# 801
-200 -	200	mbar	# 802
- 350 -	350	mbar	# 803
- 700 -	700	mbar	# 804
- 1-	1	bar	# 805
- 1-	1.4	bar	# 806
- 1 -	2	bar	# 807
- 1 -	3.5	bar	# 809
- 1 -	5	bar	#810
- 1 -	7	bar	#811
- 1 -	10	bar	# 812
- 1 -	14	bar	# 813
- 1 -	20	bar	# 814
- 1 -	30	bar	# 815
- 1 -	35	bar	# 816
0 -	40	bar	# 817
0 -	70	bar	#818
0 -	120	bar	# 819
0 -	140	bar	# 820
0 -	160	bar	# 821
0 -	200	bar	# 822
0 -	350	bar	# 823
0 -	400	bar	# 824
0 -	500	bar	# 825
0	700	hor	# 826

0-350 mbar # 853 0-350 mbar # 900 0-700 mbar # 854 0-700 mbar # 901 # 855 0-1 bar 0-1 bar # 902 0-1.4 bar 1.5 bar # 903 #856 0-0-2 bar # 857 0-2 bar # 904 # 905 3.5 bar # 859 3.5 bar 5 bar # 860 0-5 bar # 906 7 bar # 861 0-7 bar # 907 0-10 bar # 862 0-10 bar # 908

0-

# 863

# 864

# 865

#866

#867

# 868

Part No.

Differential

0- 20 bar #910 0- 35 bar #911 Comments

Maximum line pressure 35 bar

15 bar

Part No.

# 909

Pressure connection: G1/4 (female)

two adaptors are provided to convert to G1/4B (male) and 1/4NPT (male).

Differential ranges uni-directional use only

1.5 metre cable #230 a detachable PTFE cable assembly to connect the remote pressure sensors to the TRX 11  $\,$ 

### **Application**: Pressure transmitter



### Pressure switch

Abs o lute

0-

0-

0-

0-

0-

14 bar


20 bar

30 bar

35 bar

40 bar

70 bar



# TRXI

# Druck

### Standard specification

### **MEASURE**

Input	Range	1 Year Accuracy		Resolution	Remark	
mV	0100 mV	0.02%	(+)	0.01%	0.001	R - input > 20 M Ohm
	100600 mV	0.025%	(+)	0.005%	0.01	
V	06 V	0.025%	(+)	0.005%	0.0001	R - input > 1M Ohm
	660 V	0.05%	(+)	0.005%	0.001	
mA	052 mA	0.01%	(+)	0.01%	0.001	R - input 2,5 Ohm fused
Ohms	0400 Ohm	0.005%	(+)	0.02%	0.01	at 0.9 mA excitation
	4002000 Ohm	0.02%	(+)	0.015%	0.1	at 0.9 mA excitation
Frequency	0 655 Hz	0.006%			0.01	R - input > 300 k Ohm
	655 1310 Hz	0.1 Hz			0.1	R - input > 300 k Ohm
	131020,000 Hz	1 Hz			1	R - input > 300 k Ohm
Counts/minute	06 x 10 <sup>5</sup>	1 c/min.			1	R - input > 300 k Ohm
Counts/hour	010 <sup>7</sup> -1	1 c/hour			1	R - input > 300 k Ohm
Totalizing	010 <sup>8</sup> -1	infinite			1	R - input > 300 k Ohm

Accuracy (% of reading + % of range)

### SOURCE

Input	Range	1 Ye	1 Year Accuracy		Resolution	Remark	
mV	-10100 mV	0.01%	(+)	0.005%	0.001	R - ouput < 2,0 M Ohm	
V	0 12 V	0.01%	(+)	0.005%	0.0001	R - ouput < 2,0 M Ohm	
mA	0 24 mA	0.01%	(+)	0.02%	0.001	R - max 900 Ohm	
Ohms	0 400 Ohm	0.005%	(+)	0.02%	0.01	at 1 mA excitation	
	0 2000 Ohm	0.02%	(+)	0.015%	0.1	at 1 mA excitation	
Pulse	010 <sup>8</sup> -1	infinite			1	0 24V/34 mA max.	
Frequency	0 100 Hz	0.01 Hz	(+/-)	1 LSD	0.01	0 24V/34 mA max.	
	0 200,000 Hz	1 Hz			1	0 24V/34 mA max.	
pulses/min	0 6000	1 p/min			1	0 24V/34 mA max.	
pulses/min	0 99,999	36 p/hour			1	0 24V/34 mA max.	

Accuracy (% of reading + % of range)

### **TEMPERATURE**

RTD	Range	1 Year Accuracy	Resolution	
Pt1000 *1 Pt500 *1 Pt200 *1 Pt100 *1 Pt50 *1 D-100 *2 Ni100 *3 Ni120 *4 Cu10 *5	-200/400 °C -200/850 °C -200/850 °C -200/850 °C -200/850 °C -200/850 °C -80/250 °C -80/260 °C -200/640 °C	Measure 0.2 °C 0.4 °C 0.6 °C 0.3 °C 0.5 °C 0.3 °C 0.2 °C 0.2 °C 0.2 °C	Source 0.2 °C 0.4 °C 0.6 °C 0.3 °C 0.5 °C 0.3 °C 0.2 °C 0.2 °C 0.2 °C 0.2 °C	0.1 °C 0.1 °C 0.1 °C 0.03 °C 0.06 °C 0.03 °C 0.1 °C 0.1 °C 0.3 °C

\*1 = IEC 751, \*2 = JIS 1604-1989, \*3 = DIN 43760, \*4 = MINCO 7, \*5 = MINCO 16-9

Best case, Mid Range accuracies

T/C	Range	1 Year Accuracy	Resolution	
J *1 L *2 K *1 T *1 U *2 B *1 R *1 S *1 E *1 N *1	-2101200 °C -200900 °C -2701370 °C -2701370 °C -270400 °C -200600 °C -501769 °C -501769 °C -2701000 °C -2701300 °C 02320 °C 02345 °C	Measure 0.5 °C 0.3 °C 0.3 °C 0.3 °C 0.3 °C 1.0 °C 1.0 °C 1.4 °C 0.4 °C 0.6 °C 1.0 °C 1.0 °C 1.0 °C	Source 0.3 °C 0.2 °C 0.3 °C 0.2 °C 0.2 °C 0.6 °C 0.6 °C 0.7 °C 0.2 °C 0.3 °C 0.3 °C 0.5 °C	0.1 °C

\*1 = IEC 584, \*2 = DIN 43710

Best case, Mid Range accuracies

Note: Thermocouple accuracies do not include cold junction compensation errors

### SPECIAL FEATURES

## Temperature units $^{\circ}\text{C}$ or $^{\circ}\text{F}$

Temperature scales IPTS 68 or ITS 90 selectable

### Pressure units

15 units

10 programmable, 10%, 20%, 25%. Manual step or adjustable timer

Fully programmable travel time (up/down and dwell)

**Scaling** 5 digits and sign on all electrical ranges

### Temperature transmitter calibration

Both input and output readings in temperature units Calibration feature extended for all output functions

### Temperature transmitter simulation

mA output reads in temperature units

### Signal converter

Converts any input into any output, fully isolated

**Keystroking** Storage for 9 user defined test configurations

### Switch test

Display freezes on open and closed with Switch resistance measurement

Data log
1 Mbyte up to 8 Mbyte of data storage

Computer interface RS 232 and PCMCIA card

### **PCMCIA** station

PCMCIA card type 1 or 2

Language English, French, German, Italian, Portuguese and Spanish

### Power management

Auto backlight OFF, battery low indicator and status from menu.

### DISPLAY

Panel 66x40mm Graphic LCD with backlight

Typically 5 readings/second

### **ENVIRONMENTAL**

Calibration reference 22 deg.  $^{\circ}$ C  $\pm 1^{\circ}$ C, R.H. 45% + /-15%

Accuracies Accuracies true for 17 $^{\circ}$ C to 27  $^{\circ}$ C. Outside these limits add 0.0005%/ $^{\circ}$ C typically
Reference for all electrical parameters only

Temperature Operation:-10 °C to 50 °C

Humidity: 0-90% non condensing

### Sealing

Conformity EN50081-1, EN50082-1, CE Marked

Physical 1.2kg, 210x120x50mm

Power supply 4x1.5 V alkaline 'C' cells or 4 x 1.2 V Ni-Cad cells

# TRXII

# Druck


### Options and related products

### **OPTIONS**

### (A) Linkpak W calibration software P/N LinkW

Linkpak W calibration software has been developed to help meet the growing demand on industry to comply with quality systems and calibration documentation. Test procedures are created on screen in a Windows ® based utility and devices due for calibration are reported and grouped into work orders for transfer to the calibrator. Calibration results are uploaded to the PC, via the RS 232 interface or PCMCIA card, for analysis and to print calibration certificates.

For further information refer to the Linkpak W data sheet.



- B) Remote pressure sensors P/N (refer to pressure range table) Sensors from 70 mbar to 700 bar are available for use with the TRX II. The calibrator has a single remote channel which can be configured for use with up to 8 sensors (one at a time). At least one cable assembly (Part No. 230) should be ordered to connect any of the standard remote pressure sensors to the TRX II.
- C) Charger/Eliminator P/N 13603 state 110 or 230v

This adaptor has been designed with two functions. It can either power the TRX II from line voltage or it can recharge Ni-cad batteries. The charger and adaptor circuits are separate, allowing the user to recharge and operate the unit simultaneously.

### **ASSESSORIES**

The TRX II is supplied with carrying case, test leads, user guide, handbook and calibration certificate as standard.

### CALIBRATION STANDARDS

Calibrators manufactured by Druck Limited are calibrated against precision calibration equipment traceable to international standards.

### RELATED PRODUCTS

### Intecal calibration management software

Intecal Windows <sup>®</sup> based software builds on the basic concept of Linkpak W supporting laboratory and field calibrations with extensive management and analysis features. Intecal interface with a range of instruments and offers a complete solution to calibration management.

### Portable field calibrators

Druck manufacture a wide range of portable pressure, temperature and electrical field calibrators. A selection of these are shown below.



### Laboratory and workshop instruments

Druck also manufacturer a comprehensive range of pressure indicators and controllers. Included in this range are the Pressurements industrial deadweight testers and the Ruska high precision controllers and primary standard piston gauges.

### Pressure Transducers and transmitters

Druck instruments complement an extensive range of pressure transducers and transmitters, including the RTX and Smart/HART®STX process pressure transmitters.

Please refer to manufacturer for further information on related products.

### ORDERING INFORMATION

Please state the following (where applicable);

- Model number TRX II.
- 2. Options, including part numbers. For remote pressure sensors please also state the pressure range required.

Note: Options should be ordered as separate items.

Continuing development sometimes necessitates specification changes without notice.



### **Druck Limited**

Fir Tree Lane, Groby Leicester LE6 OFH England Tel: + 44 (0) 116 231 7100 Fax: + 44(0) 116 231 7103 E-mail: sales@druck.com Internet: www.druck.com Agent

SUNSTAR 商斯达实业集团是集研发、生产、工程、销售、代理经销、技术咨询、信息服务等为一体的高科技企业,是专业高科技电子产品生产厂家,是具有 10 多年历史的专业电子元器件供应商,是中国最早和最大的仓储式连锁规模经营大型综合电子零部件代理分销商之一,是一家专业代理和分銷世界各大品牌 IC 芯片和電子元器件的连锁经营綜合性国际公司,专业经营进口、国产名厂名牌电子元件,型号、种类齐全。在香港、北京、深圳、上海、西安、成都等全国主要电子市场设有直属分公司和产品展示展销窗口门市部专卖店及代理分销商,已在全国范围内建成强大统一的供货和代理分销网络。 我们专业代理经销、开发生产电子元器件、集成电路、传感器、微波光电元器件、工控机/DOC/DOM 电子盘、专用电路、单片机开发、MCU/DSP/ARM/FPGA软件硬件、二极管、三极管、模块等,是您可靠的一站式现货配套供应商、方案提供商、部件功能模块开发配套商。商斯达实业公司拥有庞大的资料库,有数位毕业于著名高校——有中国电子工业摇篮之称的西安电子科技大学(西军电)并长期从事国防尖端科技研究的高级工程师为您精挑细选、量身订做各种高科技电子元器件,并解决各种技术问题。

更多产品请看本公司产品专用销售网站:

商斯达中国传感器科技信息网: http://www.sensor-ic.com/

商斯达工控安防网: http://www.pc-ps.net/

商斯达电子元器件网: http://www.sunstare.com/

商斯达微波光电产品网:HTTP://www.rfoe.net/

商斯达消费电子产品网://www.icasic.com/

商斯达实业科技产品网://www.sunstars.cn/

传感器销售热线:

地址:深圳市福田区福华路福庆街鸿图大厦 1602 室

电话: 0755-83370250 83376489 83376549 83607652 83370251 82500323

传真: 0755-83376182 (0) 13902971329 MSN: SUNS8888@hotmail.com

邮编: 518033 E-mail:szss20@163.com QQ: 195847376

深圳赛格展销部: 深圳华强北路赛格电子市场 2583 号 电话: 0755-83665529 25059422

技术支持: 0755-83394033 13501568376

欢迎索取免费详细资料、设计指南和光盘; 产品凡多,未能尽录,欢迎来电查询。

北京分公司:北京海淀区知春路 132 号中发电子大厦 3097 号

TEL: 010-81159046 82615020 13501189838 FAX: 010-62543996

上海分公司: 上海市北京东路 668 号上海賽格电子市场 2B35 号

TEL: 021-28311762 56703037 13701955389 FAX: 021-56703037

西安分公司: 西安高新开发区 20 所(中国电子科技集团导航技术研究所)

西安劳动南路 88 号电子商城二楼 D23 号

TEL: 029-81022619 13072977981 FAX:029-88789382