


NH3-A1 Ammonia Sensor



Figure 1 NH3-A1 Schematic Diagram



Technical Specification

PERFORMANCE	Parameter	Specification	Value
	Sensitivity	nA/ppm in 50ppm NH ₃	17 to 27
	Response time	t ₉₀ (s) from zero to 50ppm NH ₃	<60
	Zero current	ppm equivalent in zero air	<20
	Resolution	RMS noise (ppm equivalent)	<0.3
	Range	ppm NH ₃ limit of performance warranty	200
	Linearity	ppm error at full scale, linear at zero and 20ppm NH ₃	+1 to -10
	Overtask limit	maximum ppm for stable response to gas pulse	1000

LIFETIME	Parameter	Specification	Value
	Zero drift	ppm equivalent change/year in lab air	<2
	Sensitivity drift	% change/year in lab air, monthly test	<3
	Operating life	months until 80% original signal (24 month warranted)	>24

ENVIRONMENTAL	Parameter	Specification	Value
	Sensitivity @ -20°C	% (output @ -20°C/output @ 20°C) @ 20ppm	ND
	Sensitivity @ 50°C	% (output @ 50°C/output @ 20°C) @ 20ppm	ND
	Zero @ -20°C	ppm equivalent change from 20°C	ND
	Zero @ 50°C	ppm equivalent change from 20°C	ND

CROSS SENSITIVITY	Gas	Sensitivity	Specification	Value
	H ₂ S	sensitivity	% measured gas @ 20ppm	<300
	NO ₂	sensitivity	% measured gas @ 20ppm	<-300
	Cl ₂	sensitivity	% measured gas @ 10ppm	<-300
	NO	sensitivity	% measured gas @ 50ppm	ND
	SO ₂	sensitivity	% measured gas @ 20ppm	ND
	CO	sensitivity	% measured gas @ 400ppm	<20
	H ₂	sensitivity	% measured gas @ 400ppm	<15
	C ₂ H ₄	sensitivity	% measured gas @ 400ppm	<ND
CO ₂	sensitivity	% measured gas @ 5%	ND	

KEY SPECIFICATIONS	Parameter	Specification	Value
	Bias voltage	mV (Working Electrode potential is above ground)	+200
	Temperature range	°C	-30 to 50
	Pressure range	kPa	80 to 120
	Humidity range	% rh continuous	15 to 90
	Storage period	months @ 3 to 20°C (stored in sealed pot)	6
	Load resistor	Ω (recommended)	10 to 47
	Weight	g	<6

NOTE: all sensors are tested at ambient environmental conditions, with 10 ohm load resistor, unless otherwise stated. As applications of use are outside our control, the information provided is given without legal responsibility. Customers should test under their own conditions, to ensure that the sensors are suitable for their own requirements.